


SMT Alignment

T. Trippe September 16, 1999

10% Test - Example Initial Configuration - Barrel 4







Alignment Strategies - tracking and geometry selections


Upper four ladders: align all four relatively

- •Select geometry elements for tracking BarLayLad = 4202,4302,4504,4804 allowed missing clusters = 0
- •Select geometry elements and degrees of freedom for alignment BarLayLad = 4202,4302,4504,4804 vary = xz

Upper four ladders: track in three, align the fourth

- •Select geometry elements for tracking BarLayLad = 4202,4302,4804 allowed missing clusters = 0
- •Select geometry elements and degrees of freedom for alignment
 BarLayLad = 4504
 vary = xz

Alignment with Constraints



Actual track

Towers aligned separately

Tracks vertex constrained

Towers constrained to single track

Alignment Strategies - tracking constraints

All eight ladders: align all eight with vertex constraint

•Select geometry elements for tracking

BarLayLad = 4202,4302,4504,4804

BarLayLad = 4205,4305,4510,4810


require one track in each, constrain to common vertex

allowed missing clusters = 0

•Select geometry elements and degrees of freedom for alignment BarLayLad = 4202,4302,4504,4804, 4205,4305,4510,4810 vary = xz

All eight ladders: align to single track

- •Select geometry elements for tracking
 BarLayLad = 4202,4302,4504,4804, 4205,4305,4510,4810
 allowed missing clusters = 0
- •Select geometry elements and degrees of freedom for alignment BarLayLad = 4202,4302,4504,4804, 4205,4305,4510,4810 vary = xz



Alignment issues from earlier discussion with Ela and Silke

- •MC generation
- •Trigger selection and rate
- Alignment Strategy
- Alignment Program Design
 - •program requirements and design
 - •use cases
 - •logical flow, data flow diagrams
 - •class diagrams
- •Interface with geometry system
- •Event reading and framework
- •Residual calculation
- Alignment parameter calculation
- Displays